

BABOUR 1: c.1890 looking SW . Original 1877 building is on right side, with 1890 addition to left of smokestack.



BABOUR 3: detail view of 1877 building gable, looking S.



BABOUR 2: Grand St. façade, looking SW. Gable end of original building is visible at right, 5-story 1910s addition to left.



BABOUR 4: close up view of 1877 building gable, looking S. this sample of meticulous brick corbelling technique is outstanding.



BABOUR 5: oblique view looking SW from Kearny St. showing Totowa Ave. façade of the 1910s addition.



BABOUR 7: overview of gable end of 1910s addition looking W from Prince St.



BABOUR 6: oblique view looking NW, showing Kearny St. façade.



BABOUR 8: looking SW, showing 2-story 1890 addition along Prince St.



BABOUR 9: oblique view looking SE of 1890 addition along Prince St. Note the rounded brick detailing in the cornice and lintels.



BABOUR 11: oblique view looking NW into 1877 building. The rolling door and trestle area at center mark the location of the Boiler House that has been removed.



BABOUR 10: oblique view looking S, showing confluence of the V-end of the courtyard area. The first addition is at right center.



BABOUR 12: close up view looking NW from interior courtyard. Note the extensive brick detail and corbelling in this view of the 1877 original building.



BABOUR 13: oblique view looking NW from corner of Prince and Slater St. showing gable end of 1890 4-story addition.



BABOUR 15: detail view looking E, showing the original building along Spring St.



BABOUR 14: oblique view looking NE, showing Spring St. side. The joint between the 1877 building and the 1890 building is evident at left of center.



BABOUR 16: looking SE, showing cast stone water table and brownstone foundation of the 1877 bld.