


## I.A. HALL MILLS

94 Fulton Street, Paterson, NJ B 3112 L 03, 04, 05

Photographs, historic / contemporary



**HALL 1:** Isaac Hall's mill on Division St. c. 1890. Hall developed a campus in that area where he expanded his mill supply business as his products became widely known. He invested profits by erecting a large tenant mill on Fulton St. c. 1899,



**HALL 2:** Oblique overview looking NW from corner of Harrison and Summer St., showing East gable ends of the twin Hall mills.



**HALL 3:** Detail view of 1910s building east gable end, looking W.



**HALL 4:** close up view of 1910s building east gable end, looking NW. Details of interest are clearly shown: meticulous brick corbelling and running course work of the closed eaves, the terra cotta coping, and the gradual-stepped buttressed pilasters.

## I.A. HALL MILLS

94 Fulton Street, Paterson, NJ B 3112 L 03, 04, 05

Photographs, historic / contemporary



**HALL 5:** oblique view looking SW from Kearny St. showing Totowa Ave. façade.



**HALL 6:** oblique view looking NW, showing Kearny St. façade.



**HALL 7:** Oblique overview looking SW from corner of Fulton and Summer St. (left side), showing East gable ends of the twin Hall mills. The c1899 mill is in the front.



**HALL 8:** detail view of 1899 building, looking S from Fulton St., showing a double bay entrance modification made to accommodate a machine shop tenant.

## I.A. HALL MILLS

94 Fulton Street, Paterson, NJ B 3112 L 03, 04, 05

Photographs, historic / contemporary



**HALL 9:** detail view of 1899 building, looking S from Fulton St., showing vinyl window replacements made to accommodate tenant reuse.



**HALL 10:** detail view of West gable end of the 1899 mill building, looking E from Straight St. The integrity of this façade is clear, including the covered original windows



**HALL 11:** close up view of West gable end of the 1899 mill building addition, looking E from Straight St. showing the Hal Mill name in sandstone lettering. The integrity of the open eaves and cornice moldings emphasizes the historic character of the mill addition.



**HALL 12:** Oblique overview looking NE. Note the vinyl replacement windows along the top floor to accommodate tenant reuse.

## I.A. HALL MILLS

94 Fulton Street, Paterson, NJ B 3112 L 03, 04, 05

Photographs, historic / contemporary



**HALL 13:** oblique overview looking SE from near corner of Fulton and Straight St. showing West gable ends of both Hall Mills. This view offers particular integrity.



**HALL 14:** oblique view looking SE, showing North side of the 1910s mill building, and view of the boiler house centralized power station at center.



**HALL 15:** oblique overview of South side of 1910s building, looking E along Harrison St., demonstrating the impressive scale and integrity of the site.



**HALL 16:** detail view of South side of 1910s building, looking N from Harrison St., showing several loading dock and entrance modifications made to accommodate tenant reuse.

## I.A. HALL MILLS

94 Fulton Street, Paterson, NJ B 3112 L 03, 04, 05

Photographs, historic / contemporary



**HALL 17:** detail view of South side of 1910s building, looking N from Harrison St., showing additional entrance modifications made to accommodate tenant reuse. These two entrances are just east of loading docks showing in Hall 16.



**HALL 18:** detail view of South side of 1910s building, looking N from Harrison St., showing brick dentils, stringcourse detailing, and use of terra cotta coping. Segmental arched windows may be extant behind the white covering material. Integrity is clear.



**HALL 19:** detail view of South side of 1910s building, looking N from Harrison St., showing consistent, reversible modifications to window openings (fenestration).



**HALL 20:** Oblique overview looking NW from corner of Harrison and Summer St., showing East gable end and Harrison St. (South) elevation of the 1910s Hall Mill.