New Jersey Department of Environmental Protection Historic Preservation Office

PROPERTY REPORT

Property ID:

1465614458

Property Name:Manhattan ShirtOwnership:PrivateAddress:111-237 River STApartment #:ZIP:07501

PROPERTY LOCATION(S):

County:	Municipality:	Local Place Name:	USGS Quad:	Block:	Lot:	
PASSAIC	Paterson		Paterson	3101	6	
PASSAIC	Paterson		Paterson	3101	8	
PASSAIC	Paterson		Paterson	3101	7	

Property Photo:



Old HSI Number: NRIS Number: HABS/HAER Number:

Description:

The Manhattan Shirt Company site consists of a U-plan brick factory building, built circa 1895 with later additions to complete the U, half of which has been heavily altered in a modern rehabilitation. A warehouse, built circa 1920, is located about one block to the northeast. Two large intervening mill buildings and a steam plant, dating to ca. 1880 and ca. 1910, which once provided continuity between the two ends of the site, have been demolished.

Setting:

The Manhattan Shirt Company is located on three tax lots that are bordered on the south by River Street and on the north by the Passaic River. The property has approximately 450 ft. of frontage on River Street between Paterson and Montgomery Streets. The setting, which was historically a mixed-use neighborhood of late 19th to early 20th century industrial and residential buildings, is now characterized by vacant lots and underutilized or vacant mill buildings, including the J.S. Sowerbutt Mills and Hinchliffe Brewery.

Survey Name:	Intensive-Level Survey of Paterson Industrial Mills		Property ID:	Page
Principal	Patrick Harshbarger	(Primary Contact)	1465614458	

Organization: Hunter Research, Inc.

Investigator:

Registration and Status Dates:

National Historic Landmark?: **National Register: New Jersey Register:**

Local Designation: Determination of Eligibility: Other Designation: Certification of Eligibility: Other Designation Date:


✓ Eligibility Worksheet included in present survey?

☐ Is this Property an identifiable farm or former farm?

SHPO Opinion:

Location Map:

Site Map:



BIBLIOGRAPHY:

Author:	Title:	Year:	HPO Accession #:	(if applicable)
Trumbull, T. R.	A History of Industrial Paterson	1882		
(None Listed)	"Shirt Notes." The Clothier and Furnisher, Vol. 42 (March 1914), p. 99.	1914		
Moody's Investment Service	Moody's Industrial Manual.	1917		
Hyde, E. B.	Atlas of Passaic County, New Jersey	1877		
Robinson, E.	Atlas of the City of Paterson, New Jersey	1884		
Robinson, E.	Atlas of the City of Paterson and Haledon, New Jersey	1899		
Mueller, A. H.	Atlas of the City of Paterson, New Jersey	1915		
Sanborn Map Company	Insurance Maps of Paterson, New Jersey	1931		
Sanborn Map Company	Insurance Maps of Paterson, New Jersey	1915		
Sanborn Map Company	Insurance Maps of Paterson, New Jersey	1899		
Sanborn Map Company	Insurance Maps of Paterson, New Jersey	1887		

Additional Information:

Intensive-Level Survey of Paterson Industrial Mills Survey Name:

Property ID: 1465614458 Page 2

Principal Patrick Harshbarger Investigator:

(Primary Contact)

Organization: Hunter Research, Inc.

More Research Need	ed? (checked=Yes)		
INTENSIVE-LEVEL US Attachments Inclu Historic District 1 District Nam Statu Associated Arch	oded: 0 Building 0 Structure 0 Object 2 not applicable	Landscape	
(known or pot	ential sites. If Yes, please describe briefly) strial archaeology (interior and mill yard)		
Conversion Problem?	ConversionNote: 25		
Date form completed:	9/7/2012		
Survey Name:	Intensive-Level Survey of Paterson Industrial Mills	Prope	rty ID: Page 3 65614458
Principal	Patrick Harshbarger	(Primary Contact) 14	300 I TT00

Principal Patrick Harshbarger **Investigator:** Organization: Hunter Research, Inc. (Primary Contact)

INDUSTRIAL BUILDING ATTACHMENT

Property ID: 1465614458

Element ID: 825324764

	1-237 River Street						
listaria Nama. Ma							
nistoric name: Ma	anufacturing Building - N	Manhattan Shirt Compar	у				
Present Use:	Industrial, light indust	rial					
Historic Industry:	Textiles						
ConstructionDate:	1895 Source :	Maps					
Construction Start Date:	1895 Constru	uction 1915 I Date:	Building ID	:			
Style:		Vernacular?					
Exterior Finish Mate	erials: Brick, Common	n Bond	Physic	cal Condition:	Fair		
Foundation Mate	erials:		Remaining H	istoric Fabric:	Low		
Roof Finish Mate	erials:		Length:	200	Stories:	4	
Structural Sy	stem:		Width:	125	Bays:	13	
Roof Sy	stem:						
Equipment/Machi	inery:						
Transportation L	inks: airstrip	loading dock	slip	1			
(checked if application	able) 🗌 dock	rail siding	oth	ner			
d the west wing were	e constructed in 1915. T	as an office and cutting/fi The building was rehabili of the lower stories of the	nishing buildin tated ca. 1970	g for garment m -80 with replace	anufacture. ment of win	dows with fixed sa	J
d the west wing were d stuccoing of the breerior Description: e interior was not ava	e constructed in 1915. Tick, with the exception of allable for inspection.	as an office and cutting/fi The building was rehabili	nishing buildin tated ca. 1970 west wing wh d 1931 Sanbo	g for garment m -80 with replace ere the windows	anufacture. ment of win s were in-fill	. The base of the Ladows with fixed sa led with stucco.	J ish
d the west wing were d stuccoing of the br erior Description: e interior was not avor, sewing machines	e constructed in 1915. Tick, with the exception of allable for inspection.	as an office and cutting/fi The building was rehabili of the lower stories of the According to the 1915 ar	nishing buildin tated ca. 1970 west wing wh d 1931 Sanbo n the 4th floor.	g for garment m -80 with replace ere the windows	anufacture. ment of win s were in-fill	. The base of the Ladows with fixed sa led with stucco.	J ish
d the west wing were d stuccoing of the brerior Description: e interior was not avor, sewing machines deration Dates:	e constructed in 1915. I ick, with the exception of ailable for inspection. A rooms on the 2nd and	as an office and cutting/fi The building was rehabili of the lower stories of the According to the 1915 ar 3rd floors, and cutting of	nishing buildin tated ca. 1970 west wing wh d 1931 Sanbo n the 4th floor.	g for garment m -80 with replace ere the windows rn maps the buil	anufacture. ment of win s were in-fill	. The base of the Ladows with fixed sa led with stucco.	J ish
d the west wing were d stuccoing of the breerior Description: e interior was not avor, sewing machines teration Dates: Alteration(s):	e constructed in 1915. I ick, with the exception of ailable for inspection. A rooms on the 2nd and Circa Date:	as an office and cutting/fi The building was rehabili of the lower stories of the According to the 1915 ar 3rd floors, and cutting of Date Range:	nishing buildin tated ca. 1970 west wing wh d 1931 Sanbo n the 4th floor.	g for garment m -80 with replace ere the windows rn maps the buil	anufacture. ment of win s were in-fill	The base of the Ladows with fixed saled with stucco.	J ish
d the west wing were d stuccoing of the brefor Description: e interior was not avor, sewing machines teration Dates: Alteration(s): Physical alteration	e constructed in 1915. I ick, with the exception of ailable for inspection. A rooms on the 2nd and Circa Date:	as an office and cutting/fi The building was rehabili of the lower stories of the According to the 1915 ar 3rd floors, and cutting or Date Range: 1915 to 198	nishing buildin tated ca. 1970 west wing wh d 1931 Sanbo n the 4th floor.	g for garment m -80 with replace ere the windows rn maps the buil	anufacture. ment of win s were in-fill	The base of the Ladows with fixed saled with stucco.	J ish
d the west wing were d stuccoing of the brerior Description: e interior was not avor, sewing machines teration Dates: Alteration(s): Physical alteration chitect/Designer:	e constructed in 1915. Tick, with the exception of ailable for inspection. A rooms on the 2nd and Circa Date:	as an office and cutting/fi The building was rehabili of the lower stories of the According to the 1915 ar 3rd floors, and cutting or Date Range: 1915 to 198	nishing buildin tated ca. 1970 west wing wh d 1931 Sanbo n the 4th floor.	g for garment m -80 with replace ere the windows rn maps the buil	anufacture. ment of win s were in-fill	The base of the Ladows with fixed saled with stucco.	J ish
d the west wing were d stuccoing of the brerior Description: e interior was not avor, sewing machines deration Dates: Alteration(s): Physical alteration chitect/Designer:	e constructed in 1915. Tick, with the exception of ailable for inspection. A rooms on the 2nd and Circa Date: 1915 10/1/201	as an office and cutting/fi The building was rehabili of the lower stories of the According to the 1915 ar 3rd floors, and cutting or Date Range: 1915 to 199	nishing buildin lated ca. 1970 e west wing who de 1931 Sanbo on the 4th floor. Sou	g for garment m -80 with replace ere the windows rn maps the buil	anufacture. ment of win s were in-fill ding house	The base of the Ladows with fixed saled with stucco. Indicate the control of the	J Ish
d the west wing were d stuccoing of the brefor Description: e interior was not avor, sewing machines deration Dates: Alteration(s): Physical alteration chitect/Designer:	e constructed in 1915. Tick, with the exception of allable for inspection. A rooms on the 2nd and Circa Date: 1915 10/1/201:	as an office and cutting/fi The building was rehabili of the lower stories of the According to the 1915 ar 3rd floors, and cutting or Date Range: 1915 to 198	nishing buildin lated ca. 1970 west wing what days a Sanboa the 4th floor. Sou OO Add	g for garment m-80 with replace the windows rn maps the build rece:	anufacture. ment of win s were in-fill ding house ng; rehabilit	The base of the Ladows with fixed saled with stucco. Indicate on the 1st the saled with stucco. Indicate on the 1st the saled with stucco.	J Ish
d the west wing were d stuccoing of the brerior Description: e interior was not avor, sewing machines deration Dates: Alteration(s): Physical alteration chitect/Designer:	e constructed in 1915. Tick, with the exception of ailable for inspection. A rooms on the 2nd and Circa Date: 1915 10/1/201	as an office and cutting/fi The building was rehabili of the lower stories of the According to the 1915 ar 3rd floors, and cutting or Date Range: 1915 to 199	nishing buildin lated ca. 1970 west wing what days a Sanboa the 4th floor. Sou OO Add	g for garment m -80 with replace ere the windows rn maps the buil	anufacture. ment of win s were in-fill ding house ng; rehabilit	The base of the Ladows with fixed saled with stucco. Indicate the control of the	J ish

INDUSTRIAL BUILDING ATTACHMENT

Property ID: 1465614458

Element ID: -385258333

Common Name: 111	-237 River Street						
Historic Name: War	ehouse - Manhattan Shirt	Company					
Present Use:							
Historic Industry:	Textiles						
ConstructionDate:	1920 Source: Ma	aps/Style					
Construction Start Date:	Constructio End Dat		Building II	D:			
Style:		☐ Vernacular?					
Exterior Finish Mater	ials: Brick, Common Bor	nd	Phys	ical Condition:	Poor		
Foundation Mater	ials:	R	Remaining F	listoric Fabric:	Medium		
Roof Finish Mater	ials:		Length:	75	Stories:	5	
Structural Sys	tem: Reinforced Concret	e Frame	Width:	75	Bays:	5	
Roof Sys	tem:						
Equipment/Machir	nery:						
Transportation Li		loading dock	sli	р			
(checked if applical	ole) dock	rail siding	Of	ther			
River Street. The buildin concrete stringcourses a loor windows have beer nterior Description:	. 1920, is a 5-story, 5-bay by the graph has a brick parapet, step and brick pilasters rising be a covered with plywood. A stable for inspection. Accordant.	ped over the end bay tween multi-light stee single non-original me	vs. The bays el sash windo etal door is l	are articulated in ows with horizont ocated in the eas	nto a grid pa ally pivoting tern bay.	attern by reinforced- g casements. First	
-	Intensive-Level Survey of	Paterson Industrial M		laine out Country (Property 1465	ID: 614458	Page 5
Principal Investigator:	Patrick Harshbarger		∐(P	rimary Contact)	1400		
Organization:	Hunter Research, Inc.						

ELIGIBILITY WORKSHEET - Properties

Property ID

1465614458

History:


The Manhattan Shirt Company began in the mid-1850s as a small garment factory operated by Sturgiss, Perkins and Wilson. In the mid-1860s, Jacob Levi, a German immigrant, purchased the factory. In 1868, the mill was described as being two stories and 25 x 100 ft. This mill was located immediately east of the stuccoed brick manufacturing building described on the industrial attachment of this form. This mill was considerably expanded in the early 1880s after Jacob Levi retired from the business giving it over to his partners, brother Louis Levi and Benjamin Wechsler. This establishment was the first to go by the name "Manhattan Shirt Company," which in 1882 was employing about 350 garment workers and producing from 12,000 to 15,000 shirts annually. The company continued to expand through the 1880s to 1910s, and by 1892 had more than doubled in size to a workforce of 850 employees, predominately women. The Manhattan Shirt Company incorporated in the State of New York in 1912 with Lewis Levi as President. This move was apparently to form a conglomerate that also controlled garment factories located in Passaic, N.J.; Salem, N.Y.; and Poultney, Vt., in addition to leased of a number of other garment factories, mostly located in New England. The Manhattan Shirt Company remained in operation through at least the early 1950s in Paterson.


Statement of Significance:


The Manhattan Shirt Company was a major Paterson employer from the 1880s to 1950s. Garment manufacture employed large number of women, providing additional wages and employment to Paterson's immigrant households. In and of itself, garment making was not distinctive to Paterson's industrial development, being an industrial sector more closely associated with New York City and parts of New England, but it was part of the Paterson landscape. Although evidence is limited, garment makers may have found it advantageous to be located near the source of silk. Although the Manhattan Shirt Company site has potential significance, its aspects of integrity have been greatly diminished due to demolitions and alterations. Roughly 50 percent of the complex has been razed including the oldest 1880s part of the complex that contained the original factory site and boiler house. The surviving mid-1890s factory with mid-1910s addition at the west end of the site has been heavily altered by application of stucco and replacement and reorientation of the windows. The warehouse at the east end of the site is the most intact resource, but it has no architectural or historical significance on its own merits.


1890s factory with mid-	est 1880s part of 1910s addition a windows. The	the complex that continued the thick	ontained the orig e site has been h	erations. Roughly 50 per nal factory site and boile leavily altered by applicate is the most intact resou	r house. The su	rviving mid d replacem	- nent
Eligibility for Ne	w Jersey and N	ational Registers:	⊖Yes No	National Registe			
Lev	vel of Significar	nce: Local	State	National	A	ВС	D
Justification of Eligibi	lity/Ineligibility	:					
decades of the 20th cer and those buildings tha	ntury. The comp t do survive hav diminished by th	lex does not retain a e been heavily altere	any of its earliest ed and are not a	m a small shop to a majo buildings, which were ra chitecturally distinguishe hat was located betweer	zed in successived. The integrity of	e expansio of design, s	ns, etting
Total Number of Atta	chments:	2					
List of Eleme	ent Names:	Manufacturing Buil Warehouse	lding				
Narrative Boundary Do	escription:						
Date Form Completed.	: 10/1/2012	?					
Survey Name:	Intensive-Leve	Survey of Paterson	n Industrial Mills		Property ID:		Page 6
Principal Investigator:	Patrick Harshl	parger		(Primary Contact)	14656144	58	
Organization:	Hunter Resear	ch. Inc.					

MANHATTAN SHIRT CO. 111-237 River St., Paterson, NJ B 3101 L 06, 07, 08 Site Development Maps 1877, 1884, 1899, 1915











MANHATTAN SHIRT CO. 111-237 River St., Paterson, NJ B 3101 L 06, 07, 08 Site Development Maps, 1931, 2006, 2010









MANHATTAN SHIRT CO. 111-237 River St., Paterson, NJ B 3101 L 06, 07, 08 Photographs, historic / contemporary



MANHATTAN 1: overview of south façade of the only remaining intact building of the complex, looking north from across River St. Note steel sash windows intact.



MANHATTAN 3: detail view of demolished area between the two extant buildings of the complex (left and right frame), looking northwest from across River St.



MANHATTAN 2: oblique overview of intact mill building, looking west along River St., showing the demolished areas of the complex on adjacent sides.



MANHATTAN 4: oblique overview of east and south elevations, looking west along River St. This is the largest mill building of the complex (U-shaped) clearly visible in site development maps. It has been heavily altered and restored.